Dobashi stone wall



Outline

The north facing section of Dobashi stone wall (opposite to Ishikawa-mon gate) was built in the 1630s.

The sections that collapsed in the 2024 Noto Peninsula Earthquake were previously repaired between the end of the Edo period and the Meiji period, using small river stones.

(Stonework Characteristics)

The river stones used measure between 50 and 60cm long. The side or bottom of the stones was partially fractured to create a joint surface with the adjacent stones.



Before earthquake



After earthquake