

30 areas damaged in the 2024 Noto Peninsula Earthquake

Damage such as the collapse of stonework or the deformation of the stone walls occurred in a total of 30 locations across Kanazawa Castle and Kenrokuen due to the 2024 Noto Peninsula Earthquake. Some of these areas are currently off-limits to visitors.

Main stone walls damaged in Kanazawa Castle and Kenrokuen



Gyokusen'inmaru stone wall



Honmaru North stone wall



Honmaru southern stone wall



Ooka-mon North Eastern stone wall



Dobashi stone wall



Tatsumi canal stone wall



Kenrokuen Sazae-yama stone wall

The stone walls are valuable cultural properties. To ensure that they are handled correctly and no academic value is lost, we are working with the help and guidance of experts in our restoration.

※Photos shown are for illustrative purposes



Recovery and storage of collapsed stones



Cultural Property Survey



Restoration plan & considerations



Reconstruction